VISIBLE EMISSION NOTA	ATIONS		· 	
Inspector: KURT	WALTER			
Date of Inspection: 2/1	/11			
Shift: 1 st Shift or 2 nd Sh	nift Ti	ime: 5100 PM		
<u>Unit</u>	Visual Inspection NORMAL or ABNORMAL		*Comments	
Visible Emission From Shaker	NOR			<u> paalitajammata, jällipijaja ja ja</u>
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS				
Inspector: RICK PA	LOMO				
Date of Inspection:	1)				
Shift: 1 st Shift or 2 nd Sh	end Ti	me: 5:00 Am			
Unit	Visual Inspection NORMAL or		Comments		
Visible Emission From Shaker	ABNORMAL NOR		<u> </u>		
Visible Emission From Discharge Conveyor System	NOR	- contractive and the cont		i	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS		_	
Inspector: KURT W	PALTER			
Date of Inspection:	2/11			
Shift: (1st Shift or 2nd Sh	ift Ti	me: 5!00 PAN		
unit (in the second of the sec	Visual Inspection <u>NORMAL</u> or ABNORMAL		Comments	
Visible Emission From Shaker	NOR	, non-Tributing and quantities description for the contract of		
Visible Emission From Discharge Conveyor System	NOR	**Describing and supplies to the supplies of t		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions:
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: RICK	PALOM	C		
Date of Inspection: 2/2	2/11			
	nift Ti	ime: 5,00AM		
Unit 1997	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments :	
Visible Emission From Shaker	NOR	(*************************************		
Visible Emission From Discharge Conveyor System	NOR	**************************************		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS		~~~~		
Inspector: RURT 1	VALTER				
Date of Inspection:	3/11				
Shift: 1 st Shift or 2 nd Sh		me: 5:00 Pr	1		
Unit	Visual Inspection <u>NOR</u> MAL or		100	mments.	
Visible Emission From Shaker	ABNORMAL OR				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS		_	
Inspector: RICK PALOMO			
Date of Inspection: 2/3/11			
Shift: 1 st Shift or 2 nd Shift Tim	5.00AM		
Unit Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	, will the realization of the control of the contro		
Visible Emission From Discharge Conveyor System	Interview of the contract of t		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS		_	
Inspector:	valte-			
Date of Inspection:	. 4-11			
Shift: (1st Shift or 2nd Sh	nift ^é Time	1705		
Unit	Visual Inspection NORMAL OF ABNORMAL		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector:	QL 1			
Date of Inspection:	2/5/11			
Shift: 1 st Shift or 2 nd Sh	nift Ti	me: 0500		
Unit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	Non	Without any		
Visible Emission From Discharge Conveyor System	Non			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS		_	
Inspector:	velte-			
- Jan 9	-//			
Shift: 1 st Shift or 2 nd Sh		1710		
	Visual Inspection NORMAL		Comments	
Visible Emission From Shaker	Normal Normal			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector:	To , ,			
Date of Inspection:	2/6/11			
Shift: 1 st Shift or 2 nd Sl	nift ' Ti	ime: @ 0500		
Unit.	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR	ani-amily		
Visible Emission From Discharge Conveyor System	Non			
		1		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS		_		
Inspector:	Walter				
Date of Inspection:					
Shift: (1 st Shift) or 2 nd Sh	nift Ti	me: 1710			
Unit	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Commen	ts	
Visible Emission From Shaker	1201	A Det form to the additional data for the form of the		and the second s	
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector: Rick PA	Lomo			
Date of Inspection: 2	/11			
Shift: 1 st Shift or 2 nd Sh	nift Ti 2n d	me: 5:00 AM		
Unit The second	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR	ANTONIO MARKANI SISTA MARKANI SIA MARKANI		
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS			
Inspector: Ku	ver lte-			
Date of Inspection: 2 -	7-11			
Shift: (1 st Shift) or 2 nd Sl	nift Ti	me: 1710		
Unit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		nments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	AHONS			
Inspector: RICK PA	Kone			
Date of Inspection:	8/11			
Shift: 1 st Shift or 2 ^{nd S} I	hift end T	ime: 5:00An		
Unit	Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NOR	Annual contract and an		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS	
Inspector: K. Walter	
Date of Inspection:	
Shift: (1st Shift) or 2nd Shift Time: 1716	
Unit Visual Inspection NORMAL OI	Comments
Visible Emission From Shaker	
Visible Emission From Discharge Conveyor System **Notation** **Discharge Conveyor System** **Notation** **Nota	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector: RICK PA	Lomo			
Date of Inspection: 2/9	/11			
Shift: 1 st Shift or 2 nd Sh	ift 2nd Ti	me: 5.00Am		
	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR	Стобильной повышений п		
Visible Emission From Discharge Conveyor System	NOR	**************************************		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS					
Inspector:						
Olak	ly					
Date of Inspection:	. I n					
20	111					
Shift: (st Shift or 2nd St	nift Ti	me: @ 17 12	2			
			0	.		
Unit	Visual			Comments		
	Inspection NORMAL	1997			100	
	MORWAL					
	ABNORMAL					
Visible Emission From Shaker						
4	Nac	gannessan				
Visible Emission From						
Discharge Conveyor System	Non	digent of the second				


- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector: Rick PA	LOMO			
Date of Inspection: 2/10	3/11			
Shift: 1 st Shift or 2 nd Sh	ift 2nd Ti	me: 5:00AM		
Unit	Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	NOK	- and compared to the control of the		
Visible Emission From Discharge Conveyor System	NOR	_encoderence and anti-independence of the contract of the cont		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS			
Inspector: Staen	1 s			
Date of Inspection:	Choli			
Shift: (1 st Shift or 2 nd St	nift Ti	me: 0 (7:00		
-Unit	TVIsual Inspection NORMAL OF ABNORMAL		Comments	
Visible Emission From Shaker	Nac	, and good the same		. Ст. од надажения при на на надажения при на надажения на надажения на надажения на надажения на надажения на На надажения на над
Visible Emission From Discharge Conveyor System	Naz	and the second s		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOT	ATIONS				
Inspector: Rick	PALOMO				
Date of Inspection: 2/1	1/11				
Shift: 1 st Shift or 2 nd Sh	ift Ti 2nd	me: 5:00 Ar			
Unit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL			Comments	
Visible Emission From Shaker	NOR	Angraphic and the state of the			
Visible Emission From Discharge Conveyor System	20R	5	-		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS			_			
Inspector:	Denil			1			
	ogel			1			
Date of Inspection:				ł			
	2/11/11			<u> </u>			
Shift: (1st Shift) or 2nd Sh	nift T	me: (2) 12	00				
		917					
Unit with the	: Visual ,				Comments		Elektrista Kulende (h. 1865)
	Inspection	100				11 July 12 11 11 11 11 11 11 11 11 11 11 11 11	
and the Edward and State	NORMAL		and the last of the same	10 and 10 an			
	or or	100					
	<u>abn</u> ormal -						
Visible Emission From Shaker	1		Α				
***	Nal	* consessed	ATOU	Down			
Visible Emission From			Ą				
Discharge Conveyor System	N 11			1			
	Neu	Company republication	A	K			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.


VISIBLE EMISSION NOTATIONS

VISIBLE EMISSION NOTA	ATIONS		
Inspector:			
Date of Inspection:			
Shift: 1 st Shift or 2 ^{na} Sh	nift Time:		
Unit	Visual Inspection NORMAL or ABNORMAL	Comments	
Visible Emission From Shaker	Nor		
Visible Emission From Discharge Conveyor System	NOR		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector:	nul			
Date of Inspection:	(11			
Shift: (1 st Shift) or 2 nd Sh	nift Ti	me: (7:00		
Unit	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Shaker	Non	pagama		
Visible Emission From Discharge Conveyor System	Non	pperson		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTA	TIONS			
Inspector: RCK	ALOMO			
Date of Inspection: 2/1	5/11			
Shift: 1 st Shift or 2 nd Sh	nift and Ti	me: 5100AM		
Unit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS					
Inspector: Stopen						
						
Date of Inspection:	,15/11					
Shift: (1st Shift or 2nd Si	nift Ti	me: () ()	:00			
Unit	Visual Inspection	ereu _n	terior de la companya de la company La companya de la co		comments	
	NORMAL .		a 1980 og skrigger en skrige. De skriger en forste skriger en	en e		
	or MABNORMAL		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Visible Emission From Shaker	ADMONIMAL		^	^ 1	4.	energy and the second s
Visible Ethiosion Foll Ollaker	Nac	_	ATOU	Down		
Visible Emission From			()			
Discharge Conveyor System	Non	in and the same of		\checkmark		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Shift: 1st Shift or 2nd Shift Time: 5:00 AM Unit Visual Comments Inspection NORMAL or **ABN**ORMAL Visible Emission From Shaker NOR Visible Emission From Discharge Conveyor System NOR

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Shift: 1st Shift or 2nd Shift Time: Unit Visual Comments Inspection NORMAL **ABN**ORMAL Visible Emission From Shaker Non Visible Emission From Non Discharge Conveyor System

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: Rick PAL	OMO			
Date of Inspection:	///1			
Shift: 1 st Shift or 2 nd Sh	6	ime: 5:00 Am		
Unit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	Nor	This Head Street Bill Market Annual Property		
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector:	,			
Date of Inspection:	2/17/11			
Shift: (1st Shift or 2nd Sh	ift Ti	me: @ 17:00		
Unit (1)	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Shaker	Nal			
Visible Emission From Discharge Conveyor System	Nor	- Specimon,		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATION	DNS			
Inspector: RCK PALL	DMC			
Date of Inspection: 2/18/) (
Shift: 1 st Shift or 2 nd Shift	Tir	me: 5:00 AM		
Unit	Visual		Comments	
	Inspection NORMAL or ABNORMAL			
Visible Emission From Shaker	UUR			
Visible Emission From Discharge Conveyor System	NOR	1 Angeles and the second secon		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector:)zv.			
Date of Inspection:	2/18/11			
Shift: (1 st Shift) or 2 nd Sh	ift Ti	me: @17:00		
Unit	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Shaker	Nar	quitages.		
Visible Emission From Discharge Conveyor System	Nor	galacon		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS Inspector: R Date of Inspection: Shift: 1st Shift or Time: 5 Am Unit Visual Comments Inspection NORMAL **ABN**ORMAL Visible Emission From Shaker Visible Emission From Discharge Conveyor System NOVE

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector:	Der			
Date of Inspection:	2/19/11			
Shift: (1st Shift) or 2nd Sl	nift Ti	me: @ 17:00		
Unit Control of the C	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR	, eggillisis		
Visible Emission From Discharge Conveyor System	Non	/Hens		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: S. Guala	>2d0			
Date of Inspection: 2/20				
Shift: 1 st Shift or 2 nd Sh	iffSecond Ti	me: SAM		
Unit.	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NDR		of land and contribute of the	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: Jamest	22-14/93			
	20-11			
Shift: 1 st Shift or 2 nd Sh	nift Ti	me: 1701		
Unit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	NOR	A CONTRACTOR OF THE PARTY OF TH		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE FMISSION NOTA	ATIONS		-	
Inspector: Rick A	LOMO			
Date of Inspection: 2/2	2/11			
Shift: 1 st Shift or 2 nd Sh	oift Ti	me: 5:00AM		
Unit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR	**COLATE SAMPANDA MANAGAMAN MANAGAMAN MANAGAMAN MANAGAMAN MANAGAMAN MANAGAMAN MANAGAMAN MANAGAMAN MANAGAMAN MA		
Visible Emission From Discharge Conveyor System	NOR	and the state of t		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS			
Inspector:	Joseph L.			
Date of Inspection:	V 2/21/11			
Shift: (1 st Shift) or 2 nd Sh	lift Ti	me: 14:00		
Unit •	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	Nol	, materia,		
Visible Emission From Discharge Conveyor System	Nac	Table 100 Pr		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Time: 5:00 AM Shift: 1st Shift or 2nd Shift 2 nd Unit Visual Comments Inspection NORMAL or **ABN**ORMAL Visible Emission From Shaker NOR Visible Emission From Discharge Conveyor System NOR

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 2/10/09

VISIBLE EMISSION NOTA	ATIONS			
Inspector:	Tha			
Date of Inspection:	2/22/11			
Shift: (1st Shift or 2nd Sh	nift Ti	me: @ 17:00		
Unit	Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	Non			
Visible Emission From Discharge Conveyor System	Nor	ууддай		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

D.1.12 Daily Visible Emissions Notations Per Each Daylight Shift

(Stack SDS 04)

VISIBLE EMISSION NOTATIONS

Visible Emission From Discharge Conveyor System

Inspector: James 1	Tederick			
Date of Inspection:	23-11			
Shift: 1st Shift or 2nd Sh	ift Time:	1700		
Unit	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Shaker				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: Rok PA	Lomo			
Date of Inspection: 2/2	4/11			
Shift: 1 st Shift or 2 nd Sh	ift 2nd Ti	me: 5:00 AM		
Unit	Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NOR	No. of the Contract of the Con		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS		
Inspector: RICK R	4600		
	5/11		
Shift: 1 st Shift or 2 nd Sh	rift) Ti	me: 5:00AM	
Unit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments
Visible Emission From Shaker	NOR	harmonimient	
Visible Emission From Discharge Conveyor System	NOR	etaticipilitioninininininininin	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: Lamer	Frederice		:	
	75-11			
Shift: 4st Shift or 2nd St	nift Ti	me: 1700		
Unit	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Shaker	Nor			ering in the formation of the self-state of the first of the self-self-self-self-self-self-self-self-
Visible Emission From Discharge Conveyor System	200			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector: R Lo~	~//			
Date of Inspection:	26/11			
Shift: 1 st Shift or 2 nd Sh)ift Ti	me: 5AM		
Unit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	Non			
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector:	Frederich			
Date of Inspection: $\partial - \partial$	96-11			
Shift: 1^{st} Shift or 2^{nd} Sh	ift Ti	me: \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Unit:	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NoR	~~~		
Visible Emission From Discharge Conveyor System	1200			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	TIONS			
Inspector: R 6	w			
Date of Inspection:	7/11			
Shift: 1 st Shift or 2 nd Sh	if l Ti	me: 5Am		
Unit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.